

# BOILER SYSTEM FAILURES

## *Analysis & Diagnostics Manual*



### EXAMPLES OF ISSUES IN SPECIFIC BOILER SYSTEM COMPONENTS

Metallurgy  
Volume 2.0 | Boiler Systems



# Table of Contents

---


<b>I. Economizers</b>	<i>Pages 2-7</i>
<b>II. Deaerators</b>	<i>Pages 8-11</i>
p. 8 Deaerator trays	
p. 8 Deaerator spray zone corrosion	
p. 9 Deaerator inlet header spray pipe failure	
p. 10 Deaerator venting - Steam flow	
p. 11 Deaerator spray valve failures	
<b>III. Firetube Boilers</b>	<i>Pages 12-14</i>
<b>IV. Watertube Boilers</b>	<i>Pages 15-30</i>
p. 15 Feedwater line deposits	
p. 16 Boiler lower crossover header deposits	
p. 17 Boiler lower drum roof deposits	
p. 18-21 Boiler tube scale, deposits, blisters/bulges	
p. 22-30 Boiler Tube Failures	
p. 22 Long term creep from overheating	
p. 22 Thick lip failure	
p. 23 Thin lip failures	
p. 24 Catastrophic failure	
p. 25 Stress cracking	
p. 25 High pressure boiler tube corrosion	
p. 26 Weld overlay repair of tube leak	
p. 27 Hydrogen damage	
p. 28-30 Flame Impingement	
<b>V. Steam Line Deposits</b>	<i>Page 31</i>
<b>VI. Mud Drum and Steam Drum Deposits</b>	<i>Page 32</i>
<b>VII. Boiler Drums and Tubes</b>	<i>Pages 33-34</i>
<b>VIII. Boiler Water Sight Glass Failure</b>	<i>Page 35</i>
<b>IX. Superheater Tubes Failures</b>	<i>Pages 36-38</i>
<b>X. Condensate Lines Corrosion</b>	<i>Pages 39-41</i>
<b>Contact Us</b>	<i>Page 42</i>

## Section I. Economizers

### Economizer Tubes



Return bends outside the flue gas envelope.



Return bends outside of gas passage.  
*External surfaces prone to corrosion if not protected from moisture*





Top view of finned economizer tubes



Section of fouled, finned economizer tubes



External deposits containing sulfur compounds—  
*from burning high sulfur oil*



Bare economizer tube sections before cleaning



Close-up after cleaning, showing external surface metal loss



Economizer tube cross section after cleaning, showing surface metal loss due to burning high sulfur #6 oil. Sulfuric acid forms on the tube surface when operating below the  $\text{H}_2\text{SO}_4$  dew point, ~ 267 °F.



Finned economizer tube failure






Tube removed and split longitudinally, before cleaning



After cleaning with inhibited HCL



Tube section, cleaned in dilute inhibited hydrochloric acid  
*Oxygen pitting evident after cleaning*



FAC in an economizer tube



## Section II. Deaerators

### Deaerator Trays & Spray Zone



Distorted and collapsed deaerator trays




Deaerator spray zone corrosion on SS shell due to high chlorides

## Deaerator Inlet Header Spray Pipe



Deaerator inlet header spray pipe failure



Deaerator inlet header spray pipe failure



## Deaerator Venting: Steam Flow



Extreme, excessive deaerator venting: Standard vent line and 4" bypass line flowing at very high rates. Root cause was the deaerator steam supply PRV stuck open, over pressurizing the system and lifting the multiport bypass relief valve. Result: 24,000 lbs. per hour of steam being wasted to atmosphere

Normal venting: 4 inch bypass valve off and more normal vent line flow after replacing the pressure reducing valve





## Deaerator Spray Valve Failures



Deaerator spray valve spring failure



Normal deaerator spray valve bell



Mechanically damaged deaerator spray valve

## Section III. Firetube Boilers



Tubes showing surface iron deposits and flash rusting



Tubes viewed from man-way, white deposits from evaporation to dryness



Oxygen pitting, before cleaning



Oxygen pitting, after cleaning





Oxygen pitting before cleaning – resulting from oxygen intrusion during offline storage



Oxygen pitting after cleaning

## Section IV. Watertube Boilers

### Feedwater Line



Feedwater line deposits – multiple hardness upsets in 100 year old system



Feedwater line deposits due to years of repetitive hardness intrusion

## Boiler Lower Crossover Header



Overhead deposits due to external protective refractory loss allowed furnace gases to penetrate to top of the header and cause steam blanketing and concentration of boiler water, localized corrosion and evaporation to dryness on internal header surface.



## Boiler Lower Drum



Deposits formed in the top of the drum due to refractory brick deterioration on the furnace floor above allowing hot combustion gases to penetrate through to top of the mud drum and cause steam blanketing and concentration of boiler water, localized corrosion and evaporation to dryness on internal drum surface. Deposits sloughed from tubes have accumulated at the bottom of the drum, partially blocking the inverted blowdown channel ports.

## Boiler Tube Scale, Deposits & Blisters/Bulges



Boiler tube with iron and silica scale



1.5" diameter wall tube from watertube boiler. Layered phosphate and iron deposits from years of multiple feedwater hardness and internal water treatment chemistry upsets.



Inclined overhead boiler tube – deposits on the inside (bottom) surface facing the furnace




Tube mineral scale removed for deposit weight density determination. Scrape and weigh method vs. glass bead blasting





Tube scale layering due to multiple feedwater hardness excursions



Internal surface scale restricted thru-wall heat transfer causing the tube metal to overheat, bulge, and ultimately fail.



Tube with as-received (top) and as-cleaned (bottom) sections



Rare example of a furnace wall tube section showing the effect of differential deposition from furnace zone radiant heat input (top side) vs. convection zone return gas passage (bottom side).

## Tube Failures: Long Term Creep & Thick Lip Failure



Generating tube elongated due to slow metal creep from long term overheating



Thick lip failure due to metal creep from long term overheating  
*Lines of stretch marks visible beside tube failure*



## Tube Failures: Thin Lip Failures



Thin lip failure due to rapid overheating



Thin lip failure due to rapid overheating

## Tube Failures: Catastrophic Failure



Crossover tube from upper header failed due to internal corrosion caused by oxygen pitting during layup. Several tubes sagged over time and were not corrected, resulting in incomplete draining of boiler water when off-line. Oxygen pitting at the internal stagnant waterline ultimately resulted in sudden tube failure.

Top back plenum section of the 650 psig field erected boiler – severe damage caused by a single tube failure. The rapid steam release from the failed tube suddenly enveloped the plenum, momentarily raised the roof of the boiler and blew out the back wall.



## Tube Failures: Stress Cracking



Stress crack opposite membrane weld, coincident with internal deposits which restricted heat transfer



Rifled, high pressure boiler generating tube, after cleaning. Damage from condenser leak introduced chlorides from the cooling water, lowered the pH and deposited copper in the valleys of the tube. Copper since removed by cleaning with inhibited HCL.



## Tube Failures: Weld Overlay Leak Repair



Heavy weld overlay to repair a tube leak



Internal tube surface cracks developed under coincident external surface weld overlay to repair a tube leak.

## Tube Failures: Hydrogen Damage



Hydrogen damage to high pressure boiler tube



Hydrogen damage to high pressure boiler tube



## Tube Failures: Flame Impingement



Flame impingement – rear wall



Flame impingement – back corner of furnace





Tube surface metal exfoliation due to flame impingement, overheating



Tube metal creep and failure due to overheating from flame impingement



Tube surface damage resulting from flame impingement



Weld overlay to repair furnace tube bulges resulting from flame impingement



## Section V. Steam Line Deposits



Deposits in 3 inch steam line, result of repeated instances of boiler water carryover




Deposits in 6 inch diameter steam line due to long term intermittent boiler water carryover



Steam line deposits



## Section VI. Mud Drum & Steam Drum Conditions



Mud drum, interior overhead view: Heavy iron, calcium and silica deposits caused by years of poor feedwater quality resulting in deposition throughout the boiler



Steam drum: Extreme, excessive quantity of scale and surface deposits

## Section VII. Boiler Drums & Tubes




Clean mud drum and tubes



Clean steam drum downcomer tubes, deposit fouled steam diffuser screen and boiler drum sidewalls





Steam drum surface deposition below waterline



Steam drum surface after two years on an internal cleanup program



## Section VIII. Boiler Water Sight Glass Failure



Boiler sight glass deterioration due to high alkalinity boiler water. Failure due to crack in protective mica shield, allowing boiler water with high hydroxide alkalinity to have direct contact with and dissolve the borosilicate glass.

## Section IX. Superheater Tube Failures



Crack initiation at radial weld



Spiral crack development



Back side of tube



Additional surface crack formation

Superheater tube showing crack initiation at surface weld, progressive spiral tube crack due to operational stress. Rear of tube shows additional crack formation in the tube metal due to stress – away from the field weld.



Finned superheater tube removed from a HSRG

Internal surface of finned SH tube showing deposits from boiler water carryover



Heavy magnetite formation in a superheater tube





Superheater tube bulges



Superheater tube internal deposits



Superheater tube failure promoted by internal surface deposits


## Section X. Condensate Lines Corrosion



Corrosion due to low pH (from carbonic acid) at the bottom of a condensate return line



Corrosion and failure on the lower surface of a horizontal line etched due to low pH when steam condensed



↑  
Loss of metal from the horizontal pipe  
surface where low pH condensate flowed →







Horizontal finned tube from wood drying kiln. Insufficient amine to raise the low condensate pH resulted in corrosion on the internal pipe surface. Beginning in the top of the tube as steam condensed,  $\text{CO}_2$  dissolved in the condensate as it formed and the acidic condensate flowed down the sides of the tube in rivulets, dissolving the steel pipe surface in the process, thinning the wall and sending iron back to the boiler. A rare example of the actual point at which steam condenses and low pH corrosion occurs.

## TREATMENT RECOMENDATIONS

---

This manual illustrates a number of issues and failures that can adversely affect operational efficiency within boiler systems. ChemTreat provides the necessary solutions and services to take corrective and preventative action against these and other types of failures.

Contact ChemTreat today and get in touch with one of our Treatment Engineers or Technical Specialists for a chemical treatment program designed specifically for the needs of your equipment and boiler systems.

### **Contact Information**

Online Form | [www.chemtreat.com/contact-us](http://www.chemtreat.com/contact-us)

Toll-free, Corporate Services | 1-800-648-4579

Telephone (Local) | 804-935-2200

### ***Headquarters Address***

ChemTreat, Inc.  
5640 Cox Road  
Glen Allen, Virginia 23060

